

Annexure D

BUILDING SAFETY CERTIFICATE

No. _____

Dated: 18.07.2025

It is certified that the existing building ST. JOSEPH'S High school (name of the building or premises) at Peda Kakani, Guntur

(address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+3					

The building is owned/occupied by ST. JOSEPH'S High school (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Roads & Buildings Dept (Name of Department/ Govt.) on 16.07.2025 (date of inspection) in the presence of T.G. Ignatius Sandhya Rani (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 16.07.2025 for a period of 1 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
2. nil
- 3.
- 4.

Issued on 16.07.2025 at Guntur by _____

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____
 Name : **EXECUTIVE ENGINEER**
 Designation : **(R&B) DIVISION, GUNTUR**

Name & Address of Department/ Office: _____

18/7/25