

**GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT**

From:
Sri C.Viswanatha Reddy, M.Tech.,
Executive Engineer,
(R&B) Division,
Guntur.

To:
The Principal,
ST'Joseph's High School,
Pedakakani,
Guntur District.

Letter No. Soundness Certificate / EC-III / GNT / 2026, Dated : 23.07.2026

Sub :- (R&B) Division, Guntur – Structural Soundness Certificates – “ST.Joseph’s High School ” Pedakakani, Guntur District – Issue - Regarding.

Ref :- 1) Representation received by ST'Joseph's High School, Pedakakani, Guntur Dated:- 13.07.2026.

* * * * *


With reference to the above, I have personally inspected the “ST'Joseph's High School” on 22.07.2026 which was located at D.No:- 4-749/1, Beside Bommidala Cancer Hospital, Main Road, NH-16, Pedakakani, Guntur District.. The Existing building is RCC framed structures (G+3).

It is observed that the doors, windows and toilets are in good condition On visual observation, it is observed that the above building is **Structurally sound as on 22.07.2026 to 21.07.2027** one year.

Encl:- Soundness Certificate.

Yours faithfully,


Executive Engineer
(R&B) Division, Guntur


25/7/26

SOUNDNESS CERTIFICATE

This is to certify that I have personally inspected the the “ST’Joseph’s High School” on 22.07.2026 which was located at D.No:- 4-749/1, Beside Bommidala Cancer Hospital, Main Road, NH-16, Pedakakani, Guntur District.. The Existing building is RCC framed structures (G+3).

It is observed that the doors, windows and toilets are in good condition On visual observation, it is observed that the above building is **Structurally sound as on 22.07.2026 to 21.07.2027** one year.




22/07/26
Executive Engineer
(R&B) Division, Guntur

23/8/26

Annexure D

BUILDING SAFETY CERTIFICATE

Lr.No:- Soundness Certificate / EC-III / GNT / 2026

Dated:- 23.07.2026

It is certified that the existing building **St Joseph's High School (CBSE)** (name of the building or premises) at Dr.No:- 4-749/1, Sri Beside Bommidala Cancer Hospital, Pedakakani, GUNTUR (address)is having block(s) /Floor (s) as per details below:

Detail of Block(s)in	Block	Block	Block	Block	Block	Block
School	(1)	(2)	(3)	(4)	(5)	(6)
No.of Floor(s) in the Block	G+ 3					

The building is owned/ occupied by **St Joseph's High School (CBSC)** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Roads & Buildings Department (Name of Department/Govt.) on **22.07.2026** (date of inspection) in the presence of **T.G.Ignatius Sandhya Rani** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 22.07.2026 for a period of **one year** in accordance With rule and subject to compliance of the specific conditions as appended.

- 1.
2. _____ NIL _____
- 3.
- 4.

Issued on **23.07.2026** at GUNTUR by

*Strikeout whichever is not applicable In case of block is more than six use separate sheet for detail.



Signature with Seal :

Name :

Designation : **EXECUTIVE ENGINEER (R&B) DIVISION, GUNTUR**

Name & Address of Department/ Office: